



State of Ohio Environmental Protection Agency

Northeast District Office

2110 E. Aurora Road
Twinsburg, Ohio 44087-1969
(216) 963-1200 (216) 425-9171
FAX (216) 487-0769

EPA Region 5 Records Ctr.



315251

George V. Voinovich
Governor

February 14, 1991

RE: U.S. STEEL CORPORATION
LORAIN COUNTY
OHD004222030

Ms. Jeanne Griffin
USEPA Region V
230 South Dearborn Street
Chicago, IL 60604

Dear Ms. Griffin:

The U.S. Steel Corporation Lorain Plant screening site inspection memo was received by this office on February 8, 1991. The site is a RCRA interim status/permit candidate. As RCRA is overseeing the site, CERCLA does not plan any further action and a screening site inspection work plan was not written.

In the event that this site ever becomes a CERCLA concern, it would be to our advantage to have some information on the status of hazardous waste units on the site. The OEPA RCRA inspector indicated that the facility has closed five hazardous waste units. They are as follows:

Unit D-2	hazardous waste landfill
S-5	drum storage area
S-12	drum storage area
S-21	two spent acid tanks
S-22	chromate storage container

The closure plans have not yet been reviewed by RCRA. The RCRA closure of the units may change the facility's status from one of TSD to that of generator. If the status does change, the facility will no longer need a permit.

If you have any questions or comments, please contact me at the Northeast office.

Sincerely,

Judith L. Teeter

Judith L. Teeter
Environmental Engineer
Division of Emergency and Remedial Response

JLT.wb

cc: Mark Besel, DERR, CO

*nothing
can release
this - should
be in flow*



*JLT
2/27/91*

